
Subject: Filled Windows

Posted by [C.Noetzel](#) on Sat, 24 Sep 2011 10:37:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi all,

I'm just going to do my first steps on 3D printing and got a problem with a drawing I made in Sktechup. When I export my drawing into the stl-format everything seems to be fine, netfabb shows everything korrekt:

After uploading my file to shapeways, some of the windows are filled:

I can't find the problem - is anyone able to give me a hint?

Thanks and best regards from Germany,
Christian

File Attachments

1) [merde02.jpg](#), downloaded 149 times

2) [netfabj.jpg](#), downloaded 147 times

Subject: Re: Filled Windows

Posted by [fx](#) on Sat, 24 Sep 2011 11:08:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

Your part needs to be repaired. Netfabb shows the red /!\ sign. You have to repair your STL by clicking on repair (little red + button in the toolbar), then "automatic repair", then "apply repair".

Subject: Re: Filled Windows

Posted by [C.Noetzel](#) on Sat, 24 Sep 2011 11:19:45 GMT

[View Forum Message](#) <> [Reply to Message](#)

OK, I thoutg the red /!\ was shown because I used an unregistered Version of netfabb, it was the first time I worked with this program.

Thank you, I hope I'm now able to repair the drawing independently.

Christian